
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 3	
Sewershed: JONES FALLS	Company: REI/DRAYCO	Date: 06/18/08
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S37QQ_028MH	Test ID: 0994-353	Notifications Made:_X (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Page 2 of 3				
Sewershed: JONES FALLS			Company: REI/DRAYCO				Date: 06/18/2008		
Test to be Performed:		Ground	Condition	:		Supervisor:E.R			
Smoke:X Dyed Water:			Dry: _X Damp: Wet:				Caporrio	<u></u>	
Manhole ID: S37QQ_028MH		Test ID: 0994-353				Notifications Made:X (Residents, Fire, 311)			
Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)									
Defect				Source			Drainage		, , , , , , , , , , , , , , , , , , ,
No.		Address		Туре	Location	Sector	Area	Severity	Photo Number
1	611 BARTLET	Γ Δ\/Ε		03	08	02	0	03	353_OB01-01
	OTT BARTLET	I AVL.		- 00	- 00	02			000_0201 01
				OBSERV	/ΔΤΙΩΝ	CODES		<u> </u>	
	Source Type	Location	Sector	Severity	ATION	Source	Location		
	Source Type	Location	Jector	Severity		Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame S	Non-Payed		
	Service Line	Paved Asphalt	Private	Trace			Field/Woods		
	Cleanout	Paved Other	TIVALE	Moderate		Catch Basin/			
	Downspout	Driveway		Major		Storm Manh			
	Area Drain	Sidewalk		ινιαμοί		Storm Ditch	Other		
	Driveway Drain	Curb				Excavation	Cuioi		
	Stairwell Drain	Yard- Front				Other			
		Yard-Back			10	Oli lei			
	Building Interior	Yard- Side							
UJ	Dananiy iikolibi	raia Olac					1		

PAGE 3 OF 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

Unique Test ID: 353	Date: 06/18/2008	Basin: JF-19
Defect No: 1	Supervisor: E.R.	Dye Test Recommended: N
House No: 611	Street Name: BARTLETT	Street Type: AVE
Source Type: 03	Location: 08	Severity: 03
Sector: 02	Drainage Area: 0	

Comments: CLEAN OUT - ABOVE GRADE. MISSING CAP.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 0994-353_OB01-01.jpg